
Cargill Marshall Landing Zones for Air Evac

Landing Zone #	Description of LZ	Photo of Area
LZ 1	SE Corner of Building. East of Shipping dock. This is a concrete surface.	
LZ 2	NE Corner of building. This is a gravel surface.	

LZ 3	NW Corner of building. By the West Barn. This is a mixture of asphalt and gravel surface.	
LZ 4	SW Corner of building. Employee Parking lot. This is an asphalt surface.	
LZ 5	Grass Field by lagoons. This is a grass surface. Please see photo below.	






LZ 1: SE Corner of Building. East of Shipping dock. This is a concrete surface.

LZ 2: NE Corner of building. This is a gravel surface.

- LZ 3: NW Corner of building. By the West Barn. This is a mixture of asphalt and gravel surface.
- LZ 4: SW Corner of building. Employee Parking lot. This is an asphalt surface.
- LZ 5: Grass Field by lagoons. This is a grass surface. Please see photo below.



If changes are made to this document, please send updated version to the following people:

Cargill Maintenance Manager

- Cargill PSM Coordinator
- Brandon Buckman Air Evac Lifeteam (brandon.buckman@air-evac.com)
- Russ Donnell Saline MRC (donner1@lpha.mopublic.org)
- Emmit Williams LEPC (emmitw@mmuonline.net)
- Tony Day Marshall Fire Department (tony-day@sbcglobal.net)

Wade Kelling – Saline County Ambulance wadek@salinecountyambulance.com

Created: 9.26.14 KK

Reviewed:

Revised: